



如何處理 The default templates are not valid 錯誤訊息

前言

有時候在使用 Simcenter Flotherm XT 匯入 3D CAD 模型時，會出現以下這個錯誤訊息，使用者該如何處理？



解決方法

The default geometry templates, *Part.prtdot* and *Assembly.asmdot*, are used by FloTHERM XT. If they have not been created, error messages will be generated.

The templates are created when a new geometry part or assembly, or a new FloTHERM XT project, has been created, but none of these operations may have taken place since installation.

Procedure

- 1. Choose **Tools > Options**.
- 1. Under the **System Options** tab, choose **Default Templates**.
- 1. Click the browse button [...] for either Parts or Assemblies (note that you only have to choose one). The New Document dialog box opens.
- 1. Click **OK** to close the New Document dialog box.
- 1. Click **OK** to close the System Options - Default Templates dialog box.

Results

The default geometry templates will have been created.

若您需要進一步的產品資料，請與本公司業務部門聯繫 02-87724131 陳小姐或 E-mail 至客服信箱 CSD@efd.com.tw 索取，謝謝！



易富迪科技股份有限公司 / 熱特性量測及功率循環實驗室：
新北市板橋區縣民大道二段 68 號 6 樓 (板橋站 2 號出口)
總機：+886-2-87724131
傳真：+886-2-29595663
實驗室：分機 1866 蔡先生

